

Link do produktu: <https://biuroparts.pl/ly5385001-oryginalna-rolka-oryginalny-separator-mp-paper-feeding-kit-do-drukarek-brother-hl-5440-hl-5450-hl-5470-hl-6180-dcp-8110-dcp-8150-dcp-8-p-3305.html>



LY5385001 - ORYGINALNA ROLKA + ORYGINALNY SEPARATOR / MP PAPER FEEDING KIT DO DRUKAREK BROTHER HL-5440 HL-5450 HL-5470 HL-6180 DCP-8110 DCP-8150 DCP-8

Cena brutto	68,88 zł
Cena netto	56,00 zł
Numer katalogowy	DRUKPARTS-LY5385001
Kod producenta	LY5385001

Opis produktu

LY5385001 - ORYGINALNA ROLKA + ORYGINALNY SEPARATOR / MP PAPER FEEDING KIT DO DRUKAREK BROTHER HL-5440 HL-5450 HL-5470 HL-6180 DCP-8110 DCP-8150 DCP-8155 MFC-8510 MFC-8710 MFC-8810 MFC-8910 MFC-8950

ZESTAW DO PODAJNIKA RĘCZNEGO MP

PASUJE DO MODELI DRUKAREK BROTHER

Brother DCP-8110DN

Brother DCP-8150DN

Brother DCP-8155DN

Brother HL-5440D

Brother HL-5450DN

Brother HL-5470DW

Brother HL-5470DWT

Brother HL-6180DW

Brother HL-6180DWT

Brother MFC-8510DN

Brother MFC-8710DW

Brother MFC-8810DW

Brother MFC-8910DW

Brother MFC-8950DW