

Link do produktu: <https://biuroparts.pl/nowe-oryginalne-sprzeglo-do-drukarek-z-serii-brother-dcp-l3510-dcp-l3517-dcp-l3551-mfc-9130-mfc-9140-mfc-9150-mfc-9330-mfc-9335-mfc-93-p-5626.html>



NOWE ORYGINALNE SPRZĘGŁO DO DRUKAREK Z SERII BROTHER DCP- L3510 / DCP-L3517 / DCP- L3551 / MFC-9130 / MFC-9140 / MFC-9150 / MFC-9330 / MFC-9335 / MFC-93

Cena brutto	45,51 zł
Cena netto	37,00 zł
Numer katalogowy	DRUKPARTS- DUP-218550
Kod producenta	DUP-218550
Kod producenta oryginalny	LR2302001 / LY6135001

Opis produktu

NOWE ORYGINALNE SPRZĘGŁO DO DRUKAREK Z SERII BROTHER DCP-L3510 / DCP-L3517 / DCP-L3551 / MFC-9130 / MFC-9140 / MFC-9150 / MFC-9330 / MFC-9335 / MFC-9340 / MFC-L3735

UWAGA: Sprzedawany produkt jest zgodny ze zdjęciem w sklepie internetowym = przed zakupem należy wymontować część z drukarki i porównać ze zdjęciem w naszym sklepie.

W większości przypadków uszkodzenia tego elementu, jest notoryczny komunikat błędu - Bęben ! --> Przesuń zieloną dźwignię na zespole bębna.

Pasuje do modeli BROTHER:

Brother HL-3140

Brother HL-3142

Brother HL-3150

Brother HL-3152

Brother HL-3170

Brother HL-3172

Brother HL-3180
Brother HL-3190
Brother DCP-9015
Brother DCP-9017
Brother DCP-9020
Brother DCP-9022
Brother MFC-9130
Brother MFC-9140
Brother MFC-9330
Brother MFC-9335
Brother MFC-9340
Brother HL-L3210
Brother HL-L3230
Brother HL-L3230
Brother HL-L3270
Brother HL-L3290C
Brother MFC-9342
Brother MFC-9350
Brother MFC-L3710
Brother MFC-L3730
Brother MFC-L3735
Brother MFC-L3745
Brother MFC-L3750
Brother MFC-L3770
Brother DCP-L3510
Brother DCP-L3517
Brother DCP-L3550
Brother DCP-L3551