

Dane aktualne na dzień: 08-10-2026 01:50

Link do produktu: <https://biuroparts.pl/nowe-oryginalne-sprzeglo-do-drukarek-z-serii-brother-hl-3140-hl-3150-hl-3160-hl-3170-hl-3180-hl-3190-hl-l3210-hl-l3230-hl-l3270-hl-l3290-dcp-9015-dcp-p-5257.html>



NOWE ORYGINALNE SPRZĘGŁO DO DRUKAREK Z SERII BROTHER HL-3140 HL-3150 HL-3160 HL-3170 HL-3180 HL-3190 HL- L3210 HL-L3230 HL-L3270 HL-L3290 DCP-9015 DCP-

Cena brutto	45,51 zł
Cena netto	37,00 zł
Numer katalogowy	DRUKPARTS-LR2302001 / LY6135001
Kod producenta	LR2302001 / LY6135001

Opis produktu

NOWE ORYGINALNE SPRZĘGŁO DO DRUKAREK Z SERII BROTHER HL-3140 HL-3150 HL-3160 HL-3170 HL-3180 HL-3190 HL-L3210 HL-L3230 HL-L3270 HL-L3290 DCP-9015 DCP-9020 DCP-9030 ... - LY6135001

UWAGA: Sprzedawany produkt jest zgodny ze zdjęciem w sklepie internetowym = przed zakupem należy wymontować część z drukarki i porównać ze zdjęciem w naszym sklepie.

W większości przypadków uszkodzenia tego elementu, jest notoryczny komunikat błędu - Bęben ! --> Przesuń zieloną dźwignię na zespole bębna.

Pasuje do modeli BROTHER:

Brother HL-3140

Brother HL-3142

Brother HL-3150

Brother HL-3152

Brother HL-3170

Brother HL-3172

Brother HL-3180

Brother HL-3190

Brother DCP-9015
Brother DCP-9017
Brother DCP-9020
Brother DCP-9022
Brother MFC-9130
Brother MFC-9140
Brother MFC-9330
Brother MFC-9335
Brother MFC-9340
Brother HL-L3210
Brother HL-L3230
Brother HL-L3230
Brother HL-L3270
Brother HL-L3290C
Brother MFC-9342
Brother MFC-9350
Brother MFC-L3710
Brother MFC-L3730
Brother MFC-L3735
Brother MFC-L3745
Brother MFC-L3750
Brother MFC-L3770
Brother DCP-L3510
Brother DCP-L3517
Brother DCP-L3550
Brother DCP-L3551