

Link do produktu: <https://biuroparts.pl/rolka-komplet-rolek-rolki-czyszczace-zespołu-grzejnego-do-drukarek-brother-dcp-9015-dcp-9017-dcp-9020-dcp-9022-dcp-9055-dcp-9270-dcp-9460-dcp-9465-p-5581.html>



## ROLKA , KOMPLET ROLEK , ROLKI CZYSZCZĄCE ZESPOŁU GRZEJNEGO DO DRUKAREK BROTHER DCP-9015 DCP-9017 DCP-9020 DCP-9022 DCP-9055 DCP-9270 DCP-9460 DCP-9465

|                           |                                  |
|---------------------------|----------------------------------|
| Cena brutto               | <b>45,51 zł</b>                  |
| Cena netto                | <b>37,00 zł</b>                  |
| Numer katalogowy          | <b>DRUKPARTS-<br/>DUP-217761</b> |
| Kod producenta            | <b>DUP-217761</b>                |
| Kod producenta oryginalny | <b>LY0634001</b>                 |

### Opis produktu

**ROLKA , KOMPLET ROLEK , ROLKI CZYSZCZĄCE ZESPOŁU GRZEJNEGO DO DRUKAREK BROTHER DCP-9015 DCP-9017 DCP-9020 DCP-9022 DCP-9055 DCP-9270 DCP-9460 DCP-9465 DCP-9560 DCP-9970 DCP-L3510 DCP-L3517 DCP-L3550 ...**

**Cena za komplet 4 szt. rolek jak na zdjęciu**

**NOWE ROLKI CZYSZCZĄCE DO REGENERACJI ZESPOŁU GRZEJNEGO**

**Pasują do następujących modeli drukarek Brother**

- Brother HL-3140
- Brother HL-3150
- Brother HL-3170
- Brother HL-3180
- Brother HL-4140
- Brother HL-4150
- Brother HL-4570
- Brother HL-L3210
- Brother HL-L3230
- Brother HL-L8250
- Brother HL-L8260
- Brother HL-L8350
- Brother HL-L8360
- Brother HL-L9200

- 
- Brother HL-L9300
  - Brother HL-L9310
  - Brother DCP-9015
  - Brother DCP-9017
  - Brother DCP-9020
  - Brother DCP-9022
  - Brother DCP-9055
  - Brother DCP-9270
  - Brother DCP-9460
  - Brother DCP-9465
  - Brother DCP-9560
  - Brother DCP-9970
  - Brother DCP-L3510
  - Brother DCP-L3517
  - Brother DCP-L3550
  - Brother DCP-L3551
  - Brother DCP-L8400
  - Brother DCP-L8410
  - Brother DCP-L8450
  - Brother MFC-9130
  - Brother MFC-9140
  - Brother MFC-9142
  - Brother MFC-9330
  - Brother MFC-9332
  - Brother MFC-9335
  - Brother MFC-9340
  - Brother MFC-9342
  - Brother MFC-9460
  - Brother MFC-9465
  - Brother MFC-9560
  - Brother MFC-9970
  - Brother MFC-L3710
  - Brother MFC-L3730
  - Brother MFC-L8600
  - Brother MFC-L8610
  - Brother MFC-L8650
  - Brother MFC-L8690
  - Brother MFC-L8850
  - Brother MFC-L8900
  - Brother MFC-L9550
  - Brother MFC-L9570

**Rolki pasują do zespołów grzewczych jak poniżej:**

D00C55001 / D01CED001 / LY0749001 / LY6753001 / LY6754001 / LR2232001 / D0135X001