

Link do produktu: <https://biuroparts.pl/rolka-komplet-rolek-rolki-czyszczace-zespołu-grzejnego-do-drukarek-brother-dcp-l8400-dcp-l8410-dcp-l8450-mfc-9130-mfc-9140-mfc-9142-mfc-9330-mfc-9-p-5582.html>



## ROLKA , KOMPLET ROLEK , ROLKI CZYSZCZĄCE ZESPOŁU GRZEJNEGO DO DRUKAREK BROTHER DCP- L8400 DCP-L8410 DCP- L8450 MFC-9130 MFC-9140 MFC-9142 MFC-9330 MFC-9

|                           |                                  |
|---------------------------|----------------------------------|
| Cena brutto               | <b>45,51 zł</b>                  |
| Cena netto                | <b>37,00 zł</b>                  |
| Numer katalogowy          | <b>DRUKPARTS-<br/>DUP-217762</b> |
| Kod producenta            | <b>DUP-217762</b>                |
| Kod producenta oryginalny | <b>LY0634001</b>                 |

### Opis produktu

**ROLKA , KOMPLET ROLEK , ROLKI CZYSZCZĄCE ZESPOŁU GRZEJNEGO DO DRUKAREK BROTHER DCP-L8400 DCP-L8410 DCP-L8450 MFC-9130 MFC-9140 MFC-9142 MFC-9330 MFC-9332 MFC-9335 MFC-9340 MFC-9342 MFC-9460 MFC-9465 ...**

**Cena za komplet 4 szt. rolek jak na zdjęciu**

**NOWE ROLKI CZYSZCZĄCE DO REGENERACJI ZESPOŁU GRZEJNEGO**

**Pasują do następujących modeli drukarek Brother**

- Brother HL-3140
- Brother HL-3150
- Brother HL-3170
- Brother HL-3180
- Brother HL-4140
- Brother HL-4150
- Brother HL-4570
- Brother HL-L3210
- Brother HL-L3230
- Brother HL-L8250
- Brother HL-L8260
- Brother HL-L8350
- Brother HL-L8360
- Brother HL-L9200

- 
- Brother HL-L9300
  - Brother HL-L9310
  - Brother DCP-9015
  - Brother DCP-9017
  - Brother DCP-9020
  - Brother DCP-9022
  - Brother DCP-9055
  - Brother DCP-9270
  - Brother DCP-9460
  - Brother DCP-9465
  - Brother DCP-9560
  - Brother DCP-9970
  - Brother DCP-L3510
  - Brother DCP-L3517
  - Brother DCP-L3550
  - Brother DCP-L3551
  - Brother DCP-L8400
  - Brother DCP-L8410
  - Brother DCP-L8450
  - Brother MFC-9130
  - Brother MFC-9140
  - Brother MFC-9142
  - Brother MFC-9330
  - Brother MFC-9332
  - Brother MFC-9335
  - Brother MFC-9340
  - Brother MFC-9342
  - Brother MFC-9460
  - Brother MFC-9465
  - Brother MFC-9560
  - Brother MFC-9970
  - Brother MFC-L3710
  - Brother MFC-L3730
  - Brother MFC-L8600
  - Brother MFC-L8610
  - Brother MFC-L8650
  - Brother MFC-L8690
  - Brother MFC-L8850
  - Brother MFC-L8900
  - Brother MFC-L9550
  - Brother MFC-L9570

**Rolki pasują do zespołów grzewczych jak poniżej:**

D00C55001 / D01CED001 / LY0749001 / LY6753001 / LY6754001 / LR2232001 / D0135X001