

Link do produktu: <https://biuroparts.pl/rolka-komplet-rolek-rolki-czyszczace-zespołu-grzejnego-do-drukarek-brother-mfc-9560-mfc-9970-mfc-l3710-mfc-l3730-mfc-l8600-mfc-l8610-mfc-l8650-mfc-p-5583.html>



ROLKA , KOMPLET ROLEK , ROLKI CZYSZCZĄCE ZESPOŁU GRZEJNEGO DO DRUKAREK BROTHER MFC-9560 MFC-9970 MFC- L3710 MFC-L3730 MFC- L8600 MFC-L8610 MFC- L8650 MFC

Cena brutto	45,51 zł
Cena netto	37,00 zł
Numer katalogowy	DRUKPARTS- DUP-217763
Kod producenta	DUP-217763
Kod producenta oryginalny	LY0634001

Opis produktu

ROLKA , KOMPLET ROLEK , ROLKI CZYSZCZĄCE ZESPOŁU GRZEJNEGO DO DRUKAREK BROTHER MFC-9560 MFC-9970 MFC-L3710 MFC-L3730 MFC-L8600 MFC-L8610 MFC-L8650 MFC-L8690 MFC-L8850 MFC-L8900 MFC-L9550 MFC-L9570 ...

Cena za komplet 4 szt. rolek jak na zdjęciu

NOWE ROLKI CZYSZCZĄCE DO REGENERACJI ZESPOŁU GRZEJNEGO

Pasują do następujących modeli drukarek Brother

- Brother HL-3140
- Brother HL-3150
- Brother HL-3170
- Brother HL-3180
- Brother HL-4140
- Brother HL-4150
- Brother HL-4570
- Brother HL-L3210
- Brother HL-L3230
- Brother HL-L8250
- Brother HL-L8260
- Brother HL-L8350
- Brother HL-L8360
- Brother HL-L9200

-
- Brother HL-L9300
 - Brother HL-L9310
 - Brother DCP-9015
 - Brother DCP-9017
 - Brother DCP-9020
 - Brother DCP-9022
 - Brother DCP-9055
 - Brother DCP-9270
 - Brother DCP-9460
 - Brother DCP-9465
 - Brother DCP-9560
 - Brother DCP-9970
 - Brother DCP-L3510
 - Brother DCP-L3517
 - Brother DCP-L3550
 - Brother DCP-L3551
 - Brother DCP-L8400
 - Brother DCP-L8410
 - Brother DCP-L8450
 - Brother MFC-9130
 - Brother MFC-9140
 - Brother MFC-9142
 - Brother MFC-9330
 - Brother MFC-9332
 - Brother MFC-9335
 - Brother MFC-9340
 - Brother MFC-9342
 - Brother MFC-9460
 - Brother MFC-9465
 - Brother MFC-9560
 - Brother MFC-9970
 - Brother MFC-L3710
 - Brother MFC-L3730
 - Brother MFC-L8600
 - Brother MFC-L8610
 - Brother MFC-L8650
 - Brother MFC-L8690
 - Brother MFC-L8850
 - Brother MFC-L8900
 - Brother MFC-L9550
 - Brother MFC-L9570

Rolki pasują do zespołów grzewczych jak poniżej:

D00C55001 / D01CED001 / LY0749001 / LY6753001 / LY6754001 / LR2232001 / D0135X001