

Link do produktu: <https://biuroparts.pl/rolka-separator-z-podajnika-recznego-tray-1-do-drukarek-hp-laserjet-m304-m305-m329-m402-m403-m426-m427-m428-m429-m501-m506-m52-p-5207.html>



ROLKA + SEPARATOR Z PODAJNIKA RĘCZNEGO TRAY 1 DO DRUKAREK HP LASERJET M304 / M305 / M329 / M402 / M403 / M426 / M427 / M428 / M429 / M501 / M506 / M52

Cena brutto	24,59 zł
Cena netto	19,99 zł
Numer katalogowy	DRUKPARTS-RL2-0656 + RL2-0657
Kod producenta	RL2-0656 + RL2-0657
Kod EAN	RL2-0656

Opis produktu

ROLKA + SEPARATOR Z PODAJNIKA RĘCZNEGO TRAY 1 DO DRUKAREK HP LASERJET M304 / M305 / M329 / M402 / M403 / M426 / M427 / M428 / M429 / M501 / M506 / M527 / M528

WYMIENI JEŚLI TWOJA DRUKARKA MA PROBLEM Z POBIERANIEM I SEPARACJĄ PAPIERU W PODAJNIKU RĘCZNYM TRAY1